



# Installation Instructions for Surface Mount ED VECTOR 0+

1. Install as per Electrical Code by a certified Electrician.
2. Screw in metal brackets to surface. Attach the wires to the power connector and strip ground wire.
3. Take the ground wire and power connector from the inside of the ED VECTOR 0+ and put it through the slot area to prepare for electrical connection.
4. Attach the power connections and use an electrical twist on connector to couple the ground wire.
5. Tuck the wires into the fixture making certain they are not pinched.
6. Snap the lighting fixture by first hooking one end to the mount connector then pushing the other end until there is a good mechanical connection. Usually a loud click will be heard when installed properly.

